



Kambič laboratorijska oprema d.o.o.
Metliška c. 16, 8333 Semič, Slovenija
Tel.: 07/35-65-220, Tel., Fax.: 07/35-65-232



ISO 9001:2000
No. 1210017274 TMS

Report No.: P11-078

Calibration report

P11-078

Climatic Chamber

KK-190CH

Ser. No.: 11033703

MEDICO SUPPORT A/S
VESTERLUNDVEJ 14B, 2tv
2730 HERLEV
Denmark

Semič, 14.04.2011

Performed by:

Anton Nagode ing.

M.P.

Approved by:

Gorazd Kambič dipl. ing.

1/34

Content:

- 1. Information about instrument and calibration**
- 2. Organization of temperature probes in the chamber**
- 3. Distribution of temperature Test -40°C**
- 4. Distribution of temperature Test 100C**
- 5. Distribution of temperature and humidity Test 90°C/85%**
- 6. Distribution of temperature and humidity Test 15°C/20%**
- 7. Distribution of temperature and humidity Test 40°C/30%**
- 8. Distribution of temperature and humidity Test 40°C/90%**
- 9. Termometers calibration**
- 10. Enclosure**

Performed by:

Anton Nagode ing.

M.P.

Approved by:

Gorazd Kambič dipl. ing.

2/34